

**ENV 25349:1992**

**Mechanical vibrations - Measurement and the assessment of human exposure to hand-transmitted vibration (ISO 5349:1986)**

Specifies general methods for measuring and reporting hand-transmitted vibration exposure in three orthogonal axes for the one-third octave bands, having centre frequencies from 6.3 to 1250 Hz, the octave bands, having centre frequencies from 8 to 1000 Hz and a frequency-weighted measure which covers the frequency range from 5.6 to 1400 Hz.